

2004 DL650

WIRING RECTIFICATION

A possible minor recall problem has been found with the 2004 DL650. It has to do with the wiring harness to the rear taillights. On some bikes the wiring harness was not properly routed and, if left in position, could chafe through and cause a short circuit.

Figure 1 shows the wiring in the incorrect position. To get to this wiring harness, the left-hand black 'L' shaped side cover and the left-hand rear fairing piece must be removed.



Figure 1

If the wiring harness is found to be incorrectly routed, it must be repositioned into the plastic cable tray provided. Figure 2 shows the wiring harness correctly positioned.



Figure 2

Some dealers have been asked to check the routing of the rear wiring harness during the first service. You should check your bike to ensure that the rear wiring harness is properly routed.